

<<<< >>>>

machine for tight  
fit to cap

<<<<<< machine here to >>>>>>  
accept a full width cap  
and bolt through sides  
and add 2 more through  
top and pin to girdle

<<<< machine here >>>>>

<<<<<

machine all  
around here