



34 Ford 4  
door sedan  
body- this is  
before I  
pulled the  
suspension





Everything was supposedly re-chromed.





Some paint coming up





Need trim kit for roof panel





Paint chips at  
rear of hood  
where hood  
has scraped.








Front left,  
under (cross  
member  
removed?)





A close-up photograph of a running board mat, likely on a vehicle. The mat is dark, possibly black or dark grey, and shows significant wear, including scuffing and discoloration. A horizontal line runs across the middle of the mat, suggesting a joint or a change in material. The background is dark and out of focus.

Some wear on both running board mats- one board was replaced, other is original and bolts are frozen.





Need to yank  
the Aerostar  
engine out...





Floor board in front of rear seat- with orange extension cord to rear lights and fuel pump



Need to patch over fuel pump- and get rid of the extension cord wiring





Rear seat back seems to be done ok- need to attach it or replace with seats that have integral seat belts (no belts yet).



Suicide doors fit and close well.





Needs dash  
work







Black vinyl  
headliner



Top needs trim  
kit





# Floor patch panel








Had a good Saturday- pulled the suspension components off.











Right, front  
to back-  
rust on the  
right  
running  
board.







Left, front to  
back



Left front rail



Gas tank





View back to front

